


















Assembly Instruction



Accessories list




	Parts	Specification	Carton	Pcs		Parts	Specification	Carton	Pcs
A		6×40	1/1	X 16	B		15×11	1/1	X 32
C		5×60	1/1	X 8	E		M3.5×14	1/1	X 5
F		M5×40	1/1	X 8	G		10×Φ40	1/1	X 5
		21mm	1/1	X 32					

Company: (mm)


1	 X1	1040x290	1/1	5	 X1	1040x290	1/1
2	 X1	1040x290	1/1	6	 X1	1040x290	1/1
3	 X1	1040x290	1/1	7	 X4	326x290	1/1
4	 X1	1040x290	1/1	8	 X2	326x290	1/1

1

Installation method of three in one rod and buckle




2



Ax4 Bx4

3


Part B connected to accessory C first rotate 90 degrees



Bx4 Cx4

4


Part B connected to accessory C first rotate 90 degrees



Bx4

5


Part B connected to accessory C first rotate 90 degrees



Bx4 Cx4


6

Part B connected to accessory C first rotate 90 degrees




Bx4

7 Now tighten the B fitting connected to the fitting C




Ax4 Bx4

8




Ax8 Bx8

9




Fx8

10



11



Ex5 Gx5

12

